



Specifications

| Specification | Value      |
|---------------|------------|
| O.D.1 [ mm ]  | 54 mm      |
| Plug          | PL_2305    |
| D.3 [ mm ]    | M10x1.5 mm |
| D.4 [ mm ]    | M10x1.5 mm |
| L.1 [ mm ]    | 193 mm     |
| COM ID        | 25         |
| Size A [ mm ] | 42.5 mm    |
| Size B [ mm ] | 21 mm      |
| Size C [ mm ] | 45.5 mm    |
| D.1 [ mm ]    | 10.50 mm   |
| D.2 [ mm ]    | 10.50 mm   |
| Voltage       | 12 V       |
| Amp           | 150 A      |
| Pulley        | AFP        |
| G [ qty. ]    | 6 qty      |

Applications

|      |
|------|
| Make |
| FORD |

Original Code

|          |               |
|----------|---------------|
| 20214    | AV6N-10300-GB |
| FG15T074 | TG15C186      |

Equivalent Code (Vehicle Manufacturer)

|                                |                                |
|--------------------------------|--------------------------------|
| SV37VA0156.0 (7 SEVEN PARTS)   | 553557RIV (KUHNER)             |
| ANM33003 (ANDEL)               | AL-109JM (JAPANPARTS)          |
| L51050 (ATL AUTOTECHNIK)       | AVA480 (AUTOTEAM)              |
| AVA480A (AUTOTEAM)             | 0986084230 (BOSCH)             |
| 1986A01210 (BOSCH)             | G107861 (BTS TURBO)            |
| 5481FB0032197 (FRANKBERG)      | CAL15480AS (CASCO)             |
| CAL15480GS (CASCO)             | 20179084BN (REAL)              |
| 20179084OE (REAL)              | 2015480.0 (SANDO)              |
| 2015480.1 (SANDO)              | 4880 (CEVAM)                   |
| 012076 (DA SILVA)              | JA012076 (DA SILVA)            |
| MAQ0487 (DA SILVA)             | 2193121502 (DRI)               |
| 28-6580 (ELSTOCK)              | 210877 (ERA)                   |
| 210877A (ERA)                  | 1648233080 (EUROREPAR)         |
| 12091009 (EUROTEC)             | A12VA0156AS (SIDAT)            |
| 9090581 (FRIESEN)              | 32084230 (HERTH+BUSS)          |
| H5515153 (HOFFER)              | 20015480AV (ITAB AUTOMOTIVE)   |
| 20015480OV (ITAB AUTOMOTIVE)   | LEA0833 (LE PART)              |
| LRA03470 (LUCAS)               | LRA3470 (LUCAS)                |
| 063730031010 (MAGNETI MARELLI) | 063731970010 (MAGNETI MARELLI) |
| MQA1970 (MAGNETI MARELLI)      | 1704769 (FORD)                 |
| 1857696 (FORD)                 | 31266149 (FORD)                |
| 31285659 (FORD)                | AV6N-10300-GB (FORD)           |
| AV6N-10300-GC (FORD)           | AV6N-10300-GD (FORD)           |
| AV6N-10300-GE (FORD)           | 5515153 (MEAT & DORIA)         |
| 4825003 (NK)                   | QRA3052 (QUINTON HAZELL)       |
| 011-003-000952R (REMANTE)      | RE73791N (THE NEWLINE)         |
| AL03087 (TMI)                  | 831010134 (TRISCAN)            |
| WAL00016 (WALKER)              | WG2196886 (WILMINK GROUP)      |
| WG2283118 (WILMINK GROUP)      | ALV7415 (KRAUF)                |
| NPANAL1122 (NAPA)              | NPANAL1146 (NAPA)              |
| NPANAL1245 (NAPA)              | AAL1122 (APEC)                 |
| AAL1146 (APEC)                 | AAL1245 (APEC)                 |
| AEK3470 (AUTOELECTRO)          | 30285659 (VOLVO)               |
| 30659390 (VOLVO)               | DRA0873 (DELCO)                |
| A3267S (AS-PL)                 | UD13570A (AS-PL)               |
| 114724 (CARGO)                 | F032114724 (CARGO)             |
| 20214N (WAI / TRANSPO)         |                                |